

Declassification Review by NGA/DoD

**S E C R E T 070203Z**

1965 APR 7 02 44Z

25X1

1. CAMERA B 101 WAS USED IN MISSION 3998 FLOWN ON 5 APRIL 1965. 7 APR 1965  
PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: OUTBOARD EDGE STATIC OCCURS INTERMITTENTLY THROUGHOUT THE MISSION. EDGE FOG IS PRESENT INTERMITTENTLY ALONG THE INBOARD EDGE. AN ABRASION 0.53" FROM THE INBOARD EDGE STARTS ON FRAME 277 AND CONTINUES THROUGH FRAME 299 AND ENDS OF THE TAIL IDENT. PLUS DENSITY SPOTS, RESEMBLING ROLLER CHATTER, OCCUR ALONG THE INBOARD EDGE FROM FRAME 1217 TO THE END OF THE MISSION. ALL EVEN NUMBERED FRAMES CONTAIN THE DATE OF 5 MARCH 1965 INSTEAD OF 5 APRIL 1965. MANUFACTURING SPLICES ARE LOCATED ON FRAME 164 AND BETWEEN FRAMES 1448 AND 1449.

C. 9L SIDE: EDGE FOG AND EDGE STATIC OCCUR INTERMITTENTLY ALONG BOTH EDGES THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE. A SMALL AREA OF FOG IS LOCATED ON THE FIRST FRAME 1.9" FROM THE OUTBOARD EDGE AND 6.0" FROM THE CLOCK EDGE. A HEAT SPLICE IS PRESENT BETWEEN FRAMES 309 AND 310. MANUFACTURING SPLICES ARE PRESENT ON FRAMES 531 AND 1671.

D. BOTH SIDES: THE LAST TITLED FRAME IS 2287.

E. THERE ARE NO MAJOR CAMERA AND PROCESSING MALFUNCTIONS.

**3. POSITIVE:**

A. THE PI SUITABILITY IS GOOD.

**SECRET**

[illegible]

# 1

25X1

-2-

B. THE PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS DEGRADED OR OBSCURED 10 PERCENT OF THE MISSION  
PHOTOGRAPHY.

S E C R E T

--END OF MESSAGE--

1